

Dimensional analysis

The Buckingham π Theorem - If there are m physical quantities containing r fundamental units, then there are $\pi = m - r$ dimensionless groups that are independent.

- Procedure:
1. Write down all relevant physical quantities and their fundamental units.
 2. Determine π .
 3. Write down the π dimensionless groups.

Example: Flow through a circular pipe

$$\frac{dP}{dx} = f(Q, R, \mu) \quad m = 4$$

$$\frac{dP}{dx} \left(\frac{\text{dynes}}{\text{cm}^3} = \frac{\text{g}}{\text{cm}^2 \text{s}^2} \right)$$

$$Q \quad (\text{cm}^3/\text{s})$$

$$R \quad (\text{cm})$$

$$\mu \left(\frac{\text{dynes}}{\text{cm}^2} \text{s} = \frac{\text{g}}{\text{cm s}} \right) \quad \text{g, cm, s} \quad r = 3$$

$$\therefore \pi = m - r = 1$$

$$\frac{1}{\mu} \frac{dP}{dx} \left(\frac{1}{\text{cm s}} \right) \quad \text{only way to get rid of grams}$$

$$\frac{1}{\mu Q} \frac{dP}{dx} \left(\frac{1}{\text{cm}^4} \right) \quad \text{only way to get rid of seconds}$$

$$\frac{R^4}{\mu Q} \frac{dP}{dx} \quad (\text{dimensionless})$$

$$\text{Dimensional Analysis} \quad \Rightarrow \quad \frac{dP}{dx} \sim \frac{\mu Q}{R^4}$$

Dimensional analysis

$$\text{Dimensional Analysis} \Rightarrow \frac{dP}{dx} \sim \frac{\mu Q}{R^4}$$

Not as useful as the exact result:

$$\frac{\Delta P}{L} = \frac{8 \mu Q}{\pi R^4}$$

because exact result has the prefactor.

How did we get so much information? **We cheated!**

Used “experience” to guess that ΔP and L would only enter as $dP/dx = \Delta P/L$, and that the velocity v would only enter through Q .

Dimensional analysis

EXAMPLE: FLOW IN AN EXTRUDER

$$\frac{dP}{dx} = f(Q, D_s, h_s, N_s, \phi_s, \mu) \quad \left(\frac{\text{g}}{\text{cm}^2 \text{s}^2} \right)$$

Q (cm^3/s) volumetric flow rate

D_s (cm) barrel diameter


h_s (cm) flight depth

N_s (1/s) screw rotation rate

ϕ_s (dimensionless) helical angle of screw

μ (g/cm s) viscosity

$$m = 7, \quad r = 3 \quad \Rightarrow \quad \pi = m - r = 4$$



Four dimensionless groups

$$\phi_s, \frac{D_s}{h_s}, \frac{Q}{N_s D_s^3}$$

$$\frac{1}{\mu} \frac{dP}{dx} \left(\frac{1}{\text{cm s}} \right) \quad (\text{cancels grams})$$

$$\frac{D_s}{\mu N_s} \frac{dP}{dx} \quad (\text{dimensionless pressure gradient})$$

Dimensional analysis

EXAMPLE: FLOW IN AN EXTRUDER

$$\frac{D_s}{\mu N_s} \frac{dP}{dx} = f(\phi_s, D_s/h_s, Q/(N_s D_s^3))$$

Optimum $\phi_s = 23^\circ$ (universally utilized)

Most extruders are geometrically similar and designed to provide a certain pressure at the die:

$$\therefore \frac{D_s}{h_s} \cong \text{constant}$$

$$\therefore \frac{D_s}{\mu N_s} \frac{dP}{dx} \cong \text{constant}$$

If other three dimensionless groups are constant, then the last one must also be constant.

Expect $Q \sim N_s D_s^3$ (not obvious)

Melt Fiber-Spinning





Fig. 15.1 Melt strand area and radius profiles in the melt drawdown region: ●, nylon 6 at 265°C and takeup velocity of 300 m/min; △, PP at 262°C and takeup velocity of 350 m/min. (Reprinted with permission from H. F. Mark, in *Rheology*, Vol. 4, F. R. Eirich, ed., Academic Press, New York, 1969.)

Melt vs. Solution Fiber-Spinning






Fig. 11-1 Schematic diagrams of spinning processes [1].

PIPE EXTRUSION: Die Swell is Crucial!



Mandrel support die (principle). 1 Mandrel tip, 2 Mandrel support, 3 Spider leg, 4 Centering screw, 5 Die ring, 6 Relaxation zone

Mandrel Supports:



Profile Extrusion







Figure 26. Extruded profiles



Sheet Processing

SHEET EXTRUSION




Fig. 5.11 Flat slit die for film extrusion. 1 Lip, 2 Choker bar, 3 Manifold, 4 Island, 5 Flex Lip, 6 Manifold, 7 Body of the die, 8 Land, 9 Choker bar (locally adjustable), 10 Lip (adjustable)






Fig. 5.12 Flat slit die for the extrusion of sheets. 1 Lip, 2 Choker bar, 3 Manifold, 4 Island, 5 Choker bar (locally adjustable), 6 Body of the die




Principle of the coathanger manifold

Sheet Processing CLAM SHELLING IN A SHEET DIE



Typical pressure distribution in a flat slit die

Figure 1: Pressure is very high (100atm) at the center of the die.




Clam shelling due to internal pressure in a flat slit die


Figure 2: High pressure causes die to creep. After extensive extrusion, sheet will be thicker in the center.

Sheet Processing

POST-DIE SHEET FORMING



(a)



(b)

Calendering Thin Sheet:




Figure 1.5 Schematic view of an inverted "L" calender plant for the production of plastic sheeting. Molten polymer is dropped into the calender system at A. Continuous sheet is formed by passing the melt between the rolls. One of the surfaces is given texture by an embossing roll, B. Thickness gauges, C, provide data for control of the process. The sheet is cooled, D, tensioned using wind-up accumulators, E, and accu-accumulated on the wind-up roll, F (Holmes-Walker, 1975).

COEXTRUSION LAYER PACKS





Figure 5-2 Typical structure of a five-layer coextrusion. Courtesy: Dow Chemical Company.

a) 6 Layer Asymmetrical



b) 7 Layer Symmetrical




Figure 5-3 Typical coextruded structures containing recycled material in additional layers. (a) Six-layer asymmetrical structure. (b) Seven-layer symmetrical structure. Courtesy: Dow Chemical Company.

COEXTRUSION BARRIER POLYMERS

Table 5-1 Barrier Properties of Commercial Polymers

Polymer	Transmission, cc mil/100 in. ² /24 h	
	Oxygen 25°C, 65% RH	Moisture Vapor 40°C, 90% RH
<u>EVOH</u>	<u>0.05-0.18</u>	<u>1.4-5.4</u>
<u>PVDC</u>	<u>0.15-0.90</u>	<u>0.1-0.2</u>
Acrylonitrile	0.80	5.0
Amorphous nylon	0.74-2.0	—
Oriented PET	2.60	1.2
Oriented nylon	2.10	9.0
Rigid PVC	14.0	3.0
LDPE	420	1.0-1.5
HDPE	150	0.4
PP	150	0.69
PS	350	7-10

Source: EVAL Co. of America. *Plastics Packaging* (July/August 1988): 19-21

EVOH (ethylene-vinyl alcohol) random copolymer with 30%E
PVDC (polyvinylidene chloride) [CH₂CCl₂]




Figure 5-5 Comparison of barrier properties of various polymers used in packaging. Barrier ratio-thickness ratio to reach equivalent barrier. Courtesy: *Plastics Engineering* (May 1986).

COEXTRUSION






Fig. 6.2 Feed block (System Dow) for bringing melt streams together before the flat slit die. 1 Flex lip, 2 Pressure bolt, 3 Cover layer material, 4 Melt channel with a flow restrictor, 5 Adapter, 6 Base layer material, 7 Main layer material



Used to form a thin barrier layer in packaging applications

Ex. Nylon / Polypropylene
(O_2 diffuses rapidly in PP)


Fig. 6.3 Flat slit die with a sliding adapter (System Reifenhäuser)




Dual slot coextrusion dies, a) Flat slit die, 1 Heat separation, 2 Pressure roll, b) Blown film die

COEXTRUSION

FOUR-HEAD SHEET COEXTRUSION



COEXTRUSION



FILM BLOWING




Fig. 7.1. Extruder and die in a film blowing unit (after Cogswell).




Fig. 7.2. Die, 'bubble', and take-off equipment in a film blowing unit.

FILM BLOWING








Figure 37. High-output line for LDPE blown film. (Photo: Windmüller und Hölscher, Lengerich, West Germany)


Die for coating the foil strips





Calibration device (block)



Section A-A
Inlet opening




Section B-B



Section C-C
Outlet

Die and calibration device for the extrusion of edging (CAB coated aluminium foil]

Wire Coating



Combination of Poiseuille flow (pressure driven) and Couette (drag) flow due to the moving wire.

More on Wire-Coating in the NEXT LECTURE

Sheet Processing THERMOFORMING

R.G. Griskey, Polymer Process Engineering, chapter 10

J. Florian, Practical Thermoforming (Marcel Dekker, 1987)

Extrude a Sheet, Clamp it, Heat it up, and ...




Fig. 10-2 Thermoforming classifications [2].

THERMOFORMING VACUUM FORMING

$$\Delta P = 1 \text{ atm.}$$





Fig. 10-8 Methods of straight vacuum forming [2].


THERMOFORMING VENTING

290 / Florian

PROPER VENTING




1A




1B

FIGURE 75 Mold with correct vacuum hole placement: (1A) forming begins satisfactorily; (1B) full detailed forming is made.

IMPROPER VENTING Molds for Thermoforming / 291



2A



2B

FIGURE 75 (continued) Mold with incorrect vacuum hole placement: (2A) forming will begin equally well; (2B) centrally located holes covered by forming plastic with some trapped air behind.

THERMOFORMING PRESSURE-ASSISTED

To exceed $\Delta P = 1$ atm. use pressurized air.




FIGURE 76 Overpressurized forming condition: (1) incoming pressure force; (2) undersized or small number of vent/vacuum holes; (3) restricted vent/vacuum channel; (4) trapped air pockets.

Avoid trapped air by using vacuum.